



Stemilt Creek Bridge 103, Channel Restoration

Questions & Answers

Updated: 1/25/2023

Q: Describe the nature of the scour damage in more detail.

A: Undermining of foundations at both inlet and outlet as well as channel degradation near the outlet. Please refer to the website link to the most current photos (Supplemental Information: www.co.chelan.wa.us/files/public-works/documents/business/CRP730%20Supplemental%20Information.pdf).

Q: Does the county envision survey as part of the project?

A: The County has a topographical survey from 2019 if needed.

Q: Does the County envision hydraulic modeling as part of the project?

A: Yes, if hydraulic modeling is required to perform scour calculations.

Q: Does the County envision any stream restoration for aquatic species as part of the project's design?

A: No stream restoration/enhancement is proposed. Steelhead presence should be taken into account for the development of the PS&E.